

I hereby certify that this correspondence is being deposited with the United States Postal Service as First Class Mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450,

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.:

Inventor(s):

6,876,214

Atty Docket: 10020111-3

Issued:

April 05, 2005

Crook et al.

Title:

METHOD AND APPARATUS FOR CONFIGURABLE HARDWARE AUGMENTED

PROGRAM GENERATION

REQUEST FOR ISSUANCE OF **CERTIFICATE OF CORRECTION** Certificate

AUG 0 8 2006

of Correction

Attn: Certificate of Correction Branch Commissioner for Patents

P.O. Box 1450

Alexandria VA 22313-1450

Sir:

Agilent Technologies, Inc., assignee of the entire interest in the above-identified patent, respectfully requests that a Certificate of Correction be issued in accordance with 37 C.F.R. 1.322 and/or 1.323.

Enclosed herewith is a completed copy of Form PTO/SB/44 describing the various errors involved in the above-identified patent.

- 1. The errors are a result of USPTO mistake. NO FEE is required.
- 2. The errors are a result of Applicant's mistake. \$100 Fee required.
- 3. The errors are a result of both USPTO and Applicant's mistakes. \$100 Fee required.

If boxes 2 or 3 above are checked, please charge the \$100.00 fee as set forth in 1.20(a), for Applicant's errors (37 C.F.R. 1.323), to our Deposit Account 50-1078. A duplicate copy of this letter is enclosed.

08/07/2006 MBERHE

00000024 501078 6876214

01 FC:1811

100.00 DA

- 1 -

AUG = 9:2006

Issuance of a Certificate of Correction to correct these errors, which occurred in good faith is therefore respectfully requested. We shall appreciate your returning to us an executed copy of this Certificate of Correction for attachment to our Letters Patent.

Respectfully submitted,

Cynthia S. Mitchel

Reg. No. 36,081

AGILENT TECHNOLOGIES, INC. Legal Department, DL 429 Intellectual Property Administration P.O. Box 7599 Loveland, Colorado 80537-0599 Phone No. (970)679-3238 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

CERTIFICATE OF CORRECTION	
	Page <u>1</u> of <u>1</u>
PATENT NO. : 6,876,214	
APPLICATION NO.: 10/634,598	
ISSUE DATE : April 5, 2005	•
INVENTOR(S) : Crook et al.	
It is certified that an error appears or errors appear in the above-identified patent and is hereby corrected as shown below:	hat said Letters Patent
In column 9, line 49, in Claim 2, after "second probe" insert plate including a second	
In column 9, line 50, in Claim 2, after "probe plate" insert , the second hole extending through the second probe plate	
In column 10, line 7, in Claim 4, delete "tile" and insert the, therefor.	
In column 10, line 9, in Claim 5, delete "A" and insert An, therefor.	

MAILING ADDRESS OF SENDER (Please do not use customer number below): **Agilent Technologies**

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

